
F I G . 1



rozon" mrozon





FIG. 2






FIG.3




FIG. 4

150
174
158





FIG.5

FIG.6A




TOYONO. WHORKYAGE

FIG.6B

LENS DRIVE DEVICE, SUSPENSION UNIT.....
SUZUKI et al Q62980
February 7, 2001
Darryl Mexic
202-293-7060
5 of 16

FIG. 7






FIG.8




FIG.9




FIG. 10






FIG. 11






TOZONO. DHOBYZGO


LENS DRIVE DEVICE, SUSPENSION UNIT...
SUZUKI et al Q62980
February 7, 2001
Parryl Mexic
202-293-7060
8 of 16


FIG.13





LENS DRIVE DEVICE, SUSPENSION UNIT.....
SUZUKI et al Q62980
February 7, 2001
Darryl Mexic
202-293-7060
9 of 16


FIG. 14














FIG. 17A

FIG. 17B

LOZONO "NFORZZEO






FIG.18


FIG.19



FOZORO" BFOBZZ60

FIG.20





09778015 .020701

FIG.21




FIG.22




FIG.23





FIG.24






FIG. 25




FIG. 26